

This road is in progress

FIELD INSPECTION REPORT

Date of Inspection : -	03/12/2020	District:	AURANGABAD
Division :	AURANGABAD	Length (km):	1.60 Km
Name of the Road:	Aurangabad Nabinagar road se Ghamharia		
Scheme/Programme:	MAINTENANCE	New Maint. Policy.	
Package No.:	NR-N/13-20 AURAD/34	Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & stones/Pavement road markings are provided and maintained	✓ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	in progress	
Satisfactory but requires Improvement (SRI)		
Unsatisfactory (U)		

Work in progress.
Site clearance, Pot patch filling.

NAME: Dinesh Prasad Singh.

H
21/12/20
(Signature) A.E

THIS ROAD IS IN PROGRESS

FIELD INSPECTION REPORT

Date of Inspection : 03/12/2020		District: AURANGABAD	
Division : AURANGABAD		Length (km): 2.50 km	
Name of the Road: Aurangabad Nabinal Road Se Rajpur			
Scheme/Programme: MAINTENANCE		New Maintenance Policy	
Package No.: MR-N/19-20 AURAB/36		Road Id No.:	
Status of the Project: Ongoing/Completed/Under Maintenance			
Work is a case of: New Connectivity/Up gradation/ Maintenance			

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No N.A
f)	Contraction Joints provided or not (CC Pavement)	Yes/No N.A
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & stones/Pavement road markings are provided and maintained	200m Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S) <i>in progress</i>	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME: - Dina Nath Rani

Dina
 03/12/2020
 (Signature)
 J.E.R.M.
 Multinagar