

FIELD INSPECTION REPORT

Date of Inspection : 3/12/20 | District: Muzaffarpur pur

Division: Muzaffarpur (Baug-1)

Name of the Road: NH 102 North Rupauli chowk to malang

Scheme/Programme: MAINTENANCE

Package No.:

Road Id No.:

Status of the Project: Ongoing/Completed/Under Maintenance *ongoing*

Work is a case of: New Connectivity/Up gradation/ Maintenance

Sl. No. Parameters to be checked Remarks

1. Pavement S S/U

a) Road Junction condition S S/U

b) Condition of Surfacing S S/U

c) Riding Quality S S/U

d) Road Camber S S/U

e) Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. Yes/No *work not started*

f) Contraction Joints provided or not (CC Pavement) Yes/No *do*

g) Compaction of flank/slope & raintcuts if any Yes/No *work not started*

2. Cross Drainage S/SRI/U

a) Condition of head walls in Hume pipe culverts including its painting S/SRI/U

b) Condition of Abutment & Wing walls, Slab in RCC culverts S/SRI/U

c) Condition of railings/slab/approach for Bridges S/SRI/U *do*

3. Road Furniture N/A

a) Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained Yes/No

4. Compliance History No

a) Status of ATR's & any others

Overall Rating : S

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

3/12/20
Signature *JL*