

27
28

FIELD INSPECTION REPORT

Date of Inspection : 5/12/20	District: MU22affrpr	
Division : MU22- East -02	Length (km): 2.45	
Name of the Road: Gogha to Hamidpur village		
Scheme/Programme: MAINTENANCE	(New maint Policy)	
Package No.:	Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance	
Work is a case of:	New Connectivity/Up gradation/ Maintenance	
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	H/A S/U
b)	Condition of Surfacing	H/A S/U
c)	Riding Quality	H/A S/U
d)	Road Camber	H/D S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No } H/A
f)	Contraction Joints provided or not (CC Pavement)	Yes/No }
g)	Compaction of flank/slope & raincuts if any	Yes/No }
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U }
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U }
c)	Condition of railings/slab/approach for Bridges	S/SRI/U }
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No } Board fixed
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Work Not Started.

Satisfactory (S)		H/A
Satisfactory but requires Improvement (SRI)		
Unsatisfactory (U)		

(Signature)

NAME: Ashutosh Kumar

DESIGNATION: A-E.