

## FIELD INSPECTION REPORT

Date of Inspection : 3 (12/20) District: Muzafferpur  
 Division : Muzafferpur East Length (km): 2,350 km  
 Name of the Road: Sarayi 9 Motipur road til binta to til binta village

Scheme/Programme: MAINTENANCE

Package No.: Road Id No.:

Status of the Project: Ongoing/Completed/Under Maintenance

Work is a case of: New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S S/U
b)	Condition of Surfacing	S S/U
c)	Riding Quality	S S/U
d)	Road Camber	S S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	N/A Yes/No
f)	Contraction Joints provided or not (CC Pavement)	N/A Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S S/SRI/U
c)	Condition of railings/slab/approach for Bridges	N/A S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	No
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)

S

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

NAME:

Shan  
3/1/2020  
JF

(Signature)