

Latitude: 26.163213
 Longitude: 84.978775
 Elevation: 94.79m
 Accuracy: 18.5m
 Time: 05-12-2020 15:00

FIELD INSPECTION REPORT

Date of Inspection :	5/12/2020	District:	Muzaffarpur
Division :	DWP Muzaffarpur	Length (km):	4.00/3.25
Name of the Road:	East of Bahadur Chak - Bhatwala Bazar R.E. Road Bhatwala Bazar		
Scheme/Programme:	MAINTENANCE		
Package No.:	R/M/11/11/13/10/18	Road Id No.:	NEB-22000-2645
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓ S/U
b)	Condition of Surfacing	✓ S/U
c)	Riding Quality	✓ S/U
d)	Road Camber	✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	✓ Yes/No
f)	Contraction Joints provided or not (CC Pavement)	✓ Yes/No
g)	Compaction of flank/slope & raincuts if any	✓ Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓ S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓ S/SRI/U
c)	Condition of railings/slab/approach for Bridges	✓ S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	- 3 -
Satisfactory but requires Improvement (SRI)	-
Unsatisfactory (U)	-

(Signature)

NAME: K.K. Gupta

DESIGNATION: A.E