

FIELD INSPECTION REPORT

Date of Inspection : 4/12/20

Division : Rajgir

District: Nalanda

Name of the Road: Rajgir chabilapur Road to Kheirga chaman
(3054 mR)

Length (km): 2.350 km.

Scheme/Programme: MAINTENANCE

Package No.: RM/NA/RAJ/19/0003

Road Id No.: NEA 220002724

Status of the Project: Ongoing/Completed/Under Maintenance


Work is a case of: New Connectivity/Up gradation/ Maintenance **on going**

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	S/U
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	Yes/No
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	S/SRI/U
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	U

Rampreesh Kumar
SE
NAME: Rajgir


4/12/20
SE
(Signature)