

FIELD INSPECTION REPORT

Date of Inspection : 4/12/20		District: ARARUA	
Division : Paragan		Length (km): 12.700 km	
Name of the Road: Binodpur to Karadiya Shesh Bhat path.			
Scheme/Programme: MAINTENANCE		Road Id No.:	
Package No.:		Road Id No.:	
Status of the Project: Ongoing/Completed/Under Maintenance		New Connectivity/Up gradation/ Maintenance	
Work is a case of:		Parameters to be checked	
Sl. No.			Remarks
1.	Pavement		on going
a)	Road Junction condition		S/U
b)	Condition of Surfacing		"
c)	Riding Quality		"
d)	Road Camber		S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		N/A
f)	Contraction Joints provided or not (CC Pavement)		N/A
g)	Compaction of flank/slope & raincuts if any		N/A
2.	Cross Drainage		N/A
a)	Condition of head walls in Hume pipe culverts including its painting		S/SR/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SR/U
c)	Condition of railings/slab/approach for Bridges		S/SR/U
3.	Road Furniture		on going. N/A
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		Yes/No
4.	Compliance History		
a)	Status of ATR's & any others		NO

Overall Rating :	
Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

NAME:

Binodhram Prasad Pan

De Paragan

Signature
4/12/20
J.E