

FIELD INSPECTION REPORT

Date of Inspection :	District: MADHUBANI	
Division :	Length (km): 1.300 KM	
Name of the Road: NDR-10 MARHI		
Scheme/Programme:	MAINTENANCE	
Package No.:	Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance Work not started	
Work is a case of:	New Connectivity/Up gradation/ Maintenance	
Sl. No.	Parameters to be checked	Remarks
1. Pavement		
a)	Road Junction condition	S/U ✓ N/A
b)	Condition of Surfacing	S/U ✓ N/A
c)	Riding Quality	S/U ✓ N/A
d)	Road Camber	S/U ✓ N/A
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No ✓ N/A
f)	Contraction Joints provided or not (CC Pavement)	Yes/No ✓ N/A
g)	Compaction of flank/slope & raintcuts if any	Yes/No ✓ N/A
2. Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U ✓ N/A
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U ✓ N/A
c)	Condition of railings/slab/approach for Bridges	S/SRI/U ✓ N/A
3. Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ✓ N/A
4. Compliance History		
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	N/A ✓
Satisfactory but requires Improvement (SRI)	N/A ✓
Unsatisfactory (U)	N/A ✓

(Signature)
09/12/20

NAME: *Sohdeo Chawdry*

DESIGNATION: *T.E*