

# FIELD INSPECTION REPORT

(Block - Jagdishpur)

Location:	District : Bhagalpur		
Bhagalpur	Length (Km): 3.20 Km		
Name of the Road: Fulwaria - Amarpur Road.			
Scheme / Programme: MAINTENANCE			
Package No.: Group No. 12.		Road Id No.: NEA 22000445	
Status of the Project: Ongoing / Completed / Under Maintenance			
Work is a case of: New Connectivity / Up gradation / Maintenance			
SL. No.	Parameters to be checked	Remarks	
1. Pavement			
a) Road Junction condition	S/U	NA	
b) Condition of Surfacing	S/U	NA	
c) Riding Quality	S/U	NA	
d) Road Camber	S/U	NA	
e) Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes / No	NA	
f) Contraction Joints provided or not (CC Pavement)	Yes / No	NA	
g) Compaction of flank/slope & raincuts if any	Yes / No	NA	
2. Cross Drainage			
a) Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	NA	
b) Condition of Abutment & Wing Walls, Slab in RCC culverts	S/SRI/U	NA	
c) Condition of railings/slab/approach for Bridges	S/SRI/U	NA	
3. Road Furniture			
a) Whether sign boards / informative / cautionary Board / Km & 200m stones / Pavement road markings are provided and maintained.	Yes / No	NO	
4. Compliance History		NO	
a) Status of ATR's & any others		NO	
Overall Rating: Only Patch work is going on done. Work is very slow progress.			
Satisfactory (S)		—	
Satisfactory but requires Improvement (SRI)		SRI	
Unsatisfactory (U)		—	

NAME: Radha Kumar Singh  
 DESIGNATION: Assistant Engineer

Jitendra  
04/12/20  
S.E.

(Signature)

Jitendra  
04/12/20