

# FIELD INSPECTION REPORT

<b>Date of Inspection:-</b>		<b>District:- Sheohar.</b>
<b>Division:-RWD, Works Div. Sheohar</b>		<b>Length (km):- 4.650 km</b>
<b>Name of the Road:- Chatauni got to Pachra got</b>		
<b>Scheme/Programme:-</b>		<b>MAINTENANCE</b>
<b>Package No.:-</b>		<b>Road Id No.:</b>
<b>Status of the Project:</b>		<b>Ongoing/Completed/Under Maintenance</b> <i>Not Started</i>
<b>Work is a case of:</b>		<b>New Connectivity/Up gradation/ Maintenance</b>
<b>Sl. No.</b>	<b>Parameters to be checked</b>	<b>Remarks</b>
1.	<b>Pavement</b>	
a)	<b>Road Junction condition</b>	<b>S/U</b>
b)	<b>Condition of Surfacing</b>	<b>S/U</b>
c)	<b>Riding Quality</b>	<b>S/U</b>
d)	<b>Road Camber</b>	<b>S/U</b>
e)	<b>Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement</b>	<b>Yes/No</b>
f)	<b>Contraction Joints provided or not (CC Pavement)</b>	<b>Yes/No</b>
g)	<b>Compaction of flank/slope &amp; raincuts if any</b>	<b>Yes/No</b>
2.	<b>Cross Drainage</b>	
a)	<b>Condition of head walls in Hume pipe culverts including its painting</b>	<b>S/SRI/U</b>
b)	<b>Condition of Abutments &amp; Wing walls, Slab in RCC culverts</b>	<b>S/SRI/U</b>
c)	<b>Condition of railing/slab/approach for bridges</b>	<b>S/SRI/U</b>
3.	<b>Road Furniture</b>	
a)	<b>Whether sing board/informatory/cautionary Board/ Km &amp; 200m stones/Pavement road marking are provided and maintained</b>	<b>Yes/No</b>
4.	<b>Compliance History</b>	
a)	<b>Status of ATR's &amp; any others</b>	

*work is not started till now*

**Overall Rating :**

<b>Satisfactory (S)</b>	
<b>Satisfactory but requires Improvement (SRI)</b>	
<b>Unsatisfactory (U)</b>	

*(Signature)*

*1/100 5/12/20*

**Name:- Rajesh Kumar**

**DESIGNATION:- Junior Engineer**