

**FIELD INSPECTION REPORT**

| Date of Inspection: 05-12-2020               | District: ARARIA   |         |
|--|--|---------|
| Division: Porbandar                          | Length (km): 6.5 km  |         |
| Name of the Road: NH-57 Narparajam to Mirdan |  |         |
| Scheme/Programme: MAINTENANCE                |  |         |
| Package No.:                                 | Road Id No.:   |         |
| Status of the Project:                       | Ongoing/Completed/Under Maintenance  |         |
| Work is a case of:                           | New Connectivity/Up gradation/ Maintenance   |         |
| Sl. No.                                      | Parameters to be checked   | Remarks |
| <b>1. Pavement</b>                           |  |         |
| a)   | Road Junction condition  | S/U     |
| b)   | Condition of Surfacing   | S/U     |
| c)   | Riding Quality   | S/U     |
| d)   | Road Camber  | S/U     |
| e)   | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.                         | Yes/No  |
| f)   | Contraction Joints provided or not (CC Pavement)   | Yes/No  |
| g)   | Compaction of flank/slope & raincuts if any  | Yes/No  |
| <b>2. Cross Drainage</b>                     |  |         |
| a)   | Condition of head walls in Hume pipe culverts including its painting   | S/SRI/U |
| b)   | Condition of Abutment & Wing walls, Slab in RCC culverts   | S/SRI/U |
| c)   | Condition of railings/slab/approach for Bridges  | S/SRI/U |
| <b>3. Road Furniture</b>                     |  |         |
| a)   | Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained | Yes/No  |
| <b>4. Compliance History</b>                 |  |         |
| a)   | Status of ATR's & any others   |         |

Overall Rating :

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

Remark - Taken up in Priority II

05/12/2020  
15  
(Signature)

NAME: