FIELD INSPECTION REPORT

5	Inspection: O	2/12/20	
I diar	Kisha	meant-1 District: Kishanganj	
Division	f the Road:	Length(km):	
Name U	/Programme:	MAINTENANCE Now Humbergus Police	
scheme	No :	New Municipales Policy	
package	of the Project:	- 111 No. 212 a t 2 0 2 1	045
status C	o coso of:	Ongoing/Completed /Under Maintenance New Connectivity (1) 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	
	a case of:		•
51. No	stricters to be checked		Remarks
1.	raveillett		S/UV
a)	Road Junction Condition		S/UV
b)	Condition of Surfacing		S/U V
c)	Riding Quality		S/U
d)	Road Camber		s/U ✓
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		Yes/No
f)	Contraction Joints Provided or not (CC Pavement)		Yes/No
g)	Compaction of fland / shop & raincuts if any		Yes/No \
2.	Cross Drainage		
a) ,	Condition of head walls in Hume pipe culverts including its Painting		S/SRI/U
b)	Condition of Abutment & Wing walls, slab in RCC culverts		S/SRI/U
c)	Condition of railings/Slab/approach for Bridges		S/SRI/U
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		Yes/No
4.	Compliance History		
a) 1	Status of ATR's		NoT Pends
	(2)44		DT.

Overall Rating:

Satisfactory(S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory(U)

Executive Engineer

R.W.D (W) Division

Kishangani-Jutive Engineer

R.W.D. Works Division

Kishangani-1

Superintendent Engineer Work Circle Kishanganj