FIELD INSPECTION REPORT

scheme Package	f the Road: /Programme: e No.: of the Project:	MAINTENANCE New Mamberouse policy Road Id No.: 21205802 New Completed / Under Maintenance	062
	a case of:	New Connectivity/ Up gradation / Mainténance	
51. No	Parameters to be checked		Remarks
1.	Pavement		S/U
a)	Road Junction Condition		S/U
b)	Condition of Surfacing		\s/U
c)	Riding Quality		\8/U
d)	Road Camber		√S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		Yes/No
f)	Contraction Joints Provided or not (CC Pavement)		Yes/No
g)	Compaction of fland / shop & raincuts if any		✓Yes/No
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its Painting		√S/SRI/U
b)	Condition of Abutment & Wing walls, slab in RCC culverts		√S/SRI/U
c)	Condition of railings/Slab/approach for Bridges		√s/sri/U
3.	Road Furniture		
a) 🧍	Whether sign	boards/informatory/cautionary Board/km & 200m	\ Yes/No
A STATE OF THE STA	stones/Pavem	ent road markings are provided and maintained	
4.	Compliance H	istory	
a)	Status of ATR's	s & any others	Not perdi

Overall Rating:

5

Executive Engineer R.W.D (W) Division

Kishangani-1

Executive Engineer

R.W.D. Works Division

Kishangani-1

Superintendent Engineer Work Circle Kishanganj