FIELD INSPECTION

Divisio	n: Kichamarant	District: Kishanganj.	
	of the Road:	Langth/km): 7 AT	
Schem	e/Programme: MAINTE:	owk to Daula.	
	e/Programme: MAINTENANCE	M/R-3054	
Status	Cit	100	063
	-1.8011B/(.0 <sup>2</sup> /2)		
\$1. No			
1.	Pavement Parameters	to be checked	Remarks
a)	Road Junction Condition		VS/U
b)	Condition of Surfacian		U/S/U
c)	Condition of Surfacing		√s/U
d)	Riding Quality Road Camber		<i>√8/</i> U
Contract of the Contract of th			√S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		Yes/No
_f)	Contraction Joints Provided or not (CC Pavement)		Yes/No
g)	Compaction of fland / shop & raincuts if any		\Xes/No
2.	Cross Drainage		
a) i	Condition of head walls in Hume pipe culverts including its Painting		√S/SRI/U
b)	Condition of Abutment & Wing walls, slab in RCC culverts		\s/SRI/U
c)	Condition of railings/Slab/approach for Bridges		√8/SRI/U
3.	Road Furniture		V3/3KI/U
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		\Yes/No
4.	Compliance History		
a)	Status of ATR's & any others		NoTperd
			1.401

## Overall Rating:

Satisfactory(S) Satisfactory but requires Improvement (SRI) Unsatisfactory(U)

**Executive Engineer** R.W.D (W) Division

Kishanganj-1

Executive Engineer

R.W.D. Works Division

Kishanganj-1

Superintendent Engineer
Work Circle 19 Work Circle Kishanganj