

# FIELD INSPECTION REPORT

Date of Inspection: 03/12/20

Division: Kishanganj-1

District: Kishanganj

Name of the Road:

Repair of Road from Panisal to Maida.

Length(km):

Scheme/Programme:

MAINTENANCE

Package No.:

M/R-3054

Status of the Project:

Ongoing/Completed /Under Maintenance

Work is a case of:

New Connectivity/ Up gradation / Maintenance

S1. No	Parameters to be checked	Remarks
1.	<b>Pavement</b>	S/U ✓
a)	Road Junction Condition	S/U ✓
b)	Condition of Surfacing	S/U ✓
c)	Riding Quality	S/U ✓
d)	Road Camber	S/U ✓
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints Provided or not ( CC Pavement)	Yes/No
g)	Compaction of fland / shop & raincuts if any	✓ Yes/No
2.	<b>Cross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its Painting	✓ S/SRI/U
b)	Condition of Abutment & Wing walls, slab in RCC culverts	✓ S/SRI/U
c)	Condition of railings/Slab/approach for Bridges	✓ S/SRI/U
3.	<b>Road Furniture</b>	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓ Yes/No
4.	<b>Compliance History</b>	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory(S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory(U)	U

Executive Engineer  
R.W.D (W) Division  
Kishanganj-1

Executive Engineer  
R.W.D. Works Division  
Kishanganj-1

Superintendent Engineer  
Work Circle Kishanganj