FIELD INSPECTION REPORT

pate of li	NSPECTION REPORT	
Division:	1 + FD	
Name of	the Road: Dagain Length(km); 2:50 km	
Scheme/	Programme: MAINTENANCE NIR-3054.	rockla.
Package I	LIVANCE 1 DIA 2 acti	
Status of	11180 012 050	8 0+8
Work is a	b/ Complet I /II I an Maintenance	
\$1. No	Maintenance	
1.	Parameters to be checked	Remarks
		√S/U
	Road Junction Condition	VS/U
	Condition of Surfacing	√S/U
	Riding Quality	VS/U
	Road Camber	VS/U
21 1	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f) 🖟 (	Contraction Joints Provided or not ( CC Pavement)	Yes/No
g) (	Compaction of fland / shop & raincuts if any	Yes/No
2.	Cross Drainage	
a) (	Condition of head walls in Hume pipe culverts including its Painting	√S/SRI/U
b) (	Condition of Abutment & Wing walls, slab in RCC culverts	✓S/SRI/U
c) (	Condition of railings/Slab/approach for Bridges	✓S/SRI/U
3. R	Road Furniture	7,2,0
a) V	Whether sign boards/informatory/cautionary Board/km & 200m tones/Pavement road markings are provided and maintained	√Yes/No
4. C	ompliance History	
	tatus of ATR's & any others	Not perdi

## Overall Rating:

Satisfactory(S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory(U)

Executive Engineer R.W.D (W) Division

Kishanganj-1 Executive Engineer R.W.D. Works Division Kishanganj-1 Superintendent Engineer Work Circle Kishanganj