

FIELD INSPECTION REPORT

Date Of Inspection	2/12/2020	District	Bhojpur
Division	Piro	Length (km):	1.80
Name of the Road:	Sandeesh Village Bichhiya P.M.G.S. Rd to Janesarg		
Scheme/Programme	MAINTENANCE		
Package No.:	MR/19-20/Piro/15	Road Id No.:	
Status of the Project :	Ongoing/Completed/Under Maintenance		
Work is a case of :	New Connectivity/Up gradation/Maintenance		
SI No.	Parameters to be checked	Remarks	
1	Pavement	Agreement Not Done	
a)	Road Junction condition		S/U
b)	Condition of Surfacing		S/U
c)	Riding Quality		S/U
d)	Road Camber		S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement		Yes/No
f)	Contraction Joints provided or not (CC Pavement)		Yes/No
g)	Compaction of flank/slope & raincuts if any		Yes/No
2	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting		S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRI/U
c)	Condition of railings/slab/approach for Bridges		S/SRI/U
3	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		Yes/No
4	Compliance History		
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory (S)	—
Satisfactory but requires Improvement (SRI)	—
Unsatisfactory (U)	—

Name: Kamlesh Kumar

Designation J.E.

K. Kumar
2/12/2020
(Signature)