	F	ELD INSPECTION	REPORT		
				J DUY	
ivision	Piro		Length (km):	1.600 km	
lame of the Road:		Tos Sonbarsa Road to Angri		٩ .	
cheme/Programme		MAINTENANCE			
ackage	No.: AR-4/19-	20 Piro/13 R	oad Id No.:		
Status of the Project:		Ongoing/Completeted/Under Maintenance			
Work is a case of:		New Connectivity/Up	New, Connectivity/Up gradation/Maintenance		
I No.		Parameters to be checked		Remarks	
l	Parment Agreement not don				
a)	Road Junction conditi	Road Junction condition		S/U S/U	
b)	Condition of Surfacin	Condition of Surfacing			
c)	Riding Quality			S/U	
d)	Road Camber			S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement			Yes/No	
f)	Contraction Joints provided or not (CC Pavement)		Yes/No		
g)	Compaction of flank/slope & raincuts if any		Yes/No		
2	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U	
0)	Condition of railings/slab/approach for Bridges			S/SRI/U	
3	Road Furniture				
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No	
4	Compliance Histor	THE REAL PROPERTY AND PERSONS ASSESSMENT OF THE PERSONS ASSESSMENT ASSESSMENT ASSESSMENT ASSESSMENT ASSESSMENT ASSESSMENT ASSESSMENT ASSESSMENT ASSE			
a)	Status of ATR's & a	ny others			

Overa	Re	dim
CAAAC	 100	1

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Name:	aja Ombra	Kash
Designation	Executive	Engineer

(Signature) 2020