

FIELD INSPECTION REPORT

Date Of Inspection		District Bhojpur
Division Piro		Length (km): 1.700km
Name of the Road:	Am Sasaram Road to Nonar-tak	
Scheme/Programme	MAINTENANCE	
Package No.: MR-N/19-20 Piro/13	Road Id No.:	
Status of the Project :	Ongoing/Completed/Under Maintenance	
Work is a case of :	New, Connectivity/Up gradation/Maintenance	
SI No.	Parameters to be checked	Remarks
1	Pavement	Agreement not done
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & rainouts if any	Yes/No
2	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Name:

Raja Om Prakash

Designation:

Executive Engineer

(Signature)
03/12/2021