	. F	TELD INSPECTION REPOR	The second secon	1
te Of		2/2020 Dis	triot BhoTPur	1 1
vision	Piro	Let	ngth (km): 9.30	,
ame of	f the Road:	Andhari Dharampur	More to Athappa V	Mage
cheme	/Programme	MARIAIDIANIOD		road
nokage	No.: MR-N/19.	-20/ Piro/14 Road Id No.:		.,
tatus c	of the Project:	Ongoing/Completeted/Under Main		1
Vork i	s a case of :	New Connectivity/Up gradation/Iv		
I No.		Parameters to be checked	Remarks	1
	Payment	Afreement Not de	ne,	
)	Road Junction condi	ition	S/U	1
)	Condition of Surfacing		S/U	
o)	Riding Quality	S/U	١ ،	
d)	Road Camber	S/U		
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement		i aggregates Yes/No	
f)	Contraction Joints provided or not (CC Pavement)		Yes/No	
g)	Compaction of flank/slope & raincuts if any		Yes/No	_
2	Cross Drainage			
a)	Condition of head	g its painting S/SRI/U		
b)	Condition of Abuta	erts S/SRI/U		
0)	Condition of railin	S/SRI/U		
3	Road Furniture			_
8)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			
4	Compliance History			-
2)	Status of ATR's & any others			

Oversil	
(Puertal	
. , 41	

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Name:

Kamlesh Kumar

3/12/20 (Signature)

Designation

J.E.