

## FIELD INSPECTION REPORT

Date Of Inspection		District <u>BHOJPUR</u>
Division <u>Piro</u>		Length (km): <u>1.20</u>
Name of the Road:	<u>Piro Sikarhatta Main Road to Sikarhatta Kala</u>	
Scheme/Programme	MAINTENANCE	
Package No.: <u>MR-N/19-20 Piro/16</u>	Road Id No.:	
Status of the Project :	Ongoing/Completed/Under Maintenance	
Work is a case of :	New, Connectivity/Up gradation/Maintenance	
Sl No.	Parameters to be checked	Remarks
1	<b>Pavement</b> <u>Agreement not done</u>	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2	<b>Cross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3	<b>Road Furniture</b>	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4	<b>Compliance History</b>	
a)	Status of ATR's & any others	

Overall Rating

Satisfactory (S)

Satisfactory but requires Improvement (SRI)

Unsatisfactory (U)

Name:

Manoj Shrestha Prakash

Designation:

J.E.

02/12/2020  
(Signature)