ate Of	Inspection	FIELD INSPECTION REPOR	strict Bhoy'puz	
ivision	- Alro	Le	Length (km): 1.10	
ame of	the Road:	Fatchpuz kushadihra	Conal PMGSY Rose	
cheme	/Programme	MAINTENANCE		
ackage	No.: MR-N/	19-20piro/16 Road Id No.		
	of the Project :	Ongoing/Completeted/Under Ma	ntenance	
Vork is	a case of :	New Connectivity/Up gradation/	Maintenance	
I No.		Parameters to be checked	Remarks	
	Payment - Ag	riment not done	S/U	
1)	Road Junction con	anction condition		
b)	Condition of Surfa	Condition of Surfacing		
c)	Riding Quality	Riding Quality		
d)	Road Camber		S/U	
e)	Whether free from	defects such as visible cracks, expose ement	d aggregates Yes/No	
f)	Contraction Joints provided or not (CC Pavement)		Yes/No	
g)	Compaction of flank/slope & raincuts if any		Yes/No	
2	Cross Drainage			
a)	Condition of hea	Condition of head walls in Hume pipe culverts including its painting		
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		verts S/SRI/U	
0)	Condition of rail	ngs/slab/approach for Bridges	S/SRI/U	
3	Road Furniture			
2)	Whether sign bostones/Pavement	ards/informatory/cautionary Board/km road markings are provided and main	& 200m Yes/No ained	
4	Compliance His	tory		
2)	Status of ATR's	& any others		

() AGLED BYRING	Rating	Oversil
-----------------	--------	---------

Satisfactory (S) Satisfactory but requires Improvement (SRI) Unsatisfactory (U)

Name: - Mang's Lantor Pratewh.

Designation J. E.

(Signature)