ate Of	Inspection	FIELD INSPECTION RE	District Bho	ipus.	
Division fire Length (km):				.40	
ame of	f the Road:	Federings Kusha	Fatehpur Kushadihra PMBSY Road		
Scheme/Programme		MAINTENANCE			
aokage	No.: MR-N/I	9-20 pire/16 Road Id	No.:		
Status of the Project :		Ongoing/Completeted/Under Maintenance			
Work is a case of:		New,Connectivity/Up gradation/Maintenance			
I No.		Parameters to be checked	;	Remarks	
ı	Payment Ag	riment, not don	~		
a)	Road Junction condition			S/U	
b)	Condition of Surfacing			S/U	
c)	Riding Quality			S/U	
d)	Road Camber			S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement			Yes/No	
f)	Contraction Joints provided or not (CC Pavement)			Yes/No	
g)	Compaction of flank/slope & raincuts if any			Yes/No	
2	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U	
0)	Condition of railings/slab/approach for Bridges			S/SRI/U	
3	Road Furniture				
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No	
4	Compliance His	tory			
a)	Status of ATR's	& any others			

Overall Rating	V 1 - 4 - 7 - 7 - 7	Satisfactory (S)	
		Satisfactory but requires Improvement (SRI)	
		Unsatisfactory (U)	00

Manne: - Mongy Shorter Problem. J. E.