FIELD INSPECTION REPORT

Date of Inspection: 05-12-2020 Division: Bayana		District: West Chamberran Length (km): 8.35 Km
Scheme/Programme:	MAINTENANC	E - MR) 3054 (New Maintenance Policy)
Package No.: RM/WI		
The state of the s	Ongoing/Completed/Under Maintenance	
Work is a case of:	The second secon	ty/Up gradation/ Maintenance

North is a case of the Connectivity of graduation Maintenance			
Sl. No.	Parameters to be checked	Remark	
1.	Pavement		
a)	Road Junction condition		
b)	Condition of Surfacing		
c)	Riding Quality		
d)	Road Camber	S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	Xes/No	
(g)	Compaction of flank/slope & raincuts if any		
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting		
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/V	
c)	Condition of railings/slab/approach for Bridges	S/SRI/W	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		
4.	Compliance History		
a)	Status of ATR's & any others		

Overall Rating

Satisfactory (S)	-
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	~

Afrencot done But work note Started.

Man OSTINATORO (Signature)

NAME: MD. Shehanshih Alam

DESIGNATION: J.E