

FIELD INSPECTION REPORT

Date of Inspection: 05-12-2020	District: West Champaran
Division: BAGHAHA-1	Length (km): 1.00 Km
Name of the Road: Sathli Panchayat antargat Parhami gaon se Pandai Nadi se hote hue Bettiah	
Scheme/Programme: MAINTENANCE	Harkotiyaagang mukhaya Mang Tak.
Package No.: RM / WE / BAG / 19 / 0020	Road No.:
Status of the Project: ☒ Ongoing/ ☐ Completed/ ☐ Under Maintenance	
Work is a case of: ☒ New Connectivity/ ☐ Up gradation/ ☐ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ☒
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	SRI
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Note: Patch work in progress

[Signature]
5/12/20
(Signature)

NAME: BIR LAL Pd JALNAL

DESIGNATION: A.E.