

FIELD INSPECTION REPORT

Date of Inspection : 05.12.20		District: East Champaran	
Division : Paxau		Length (km): 3.0 KM	
Name of the Road: pWD Janata chaur to Tinkon			
Scheme/Programme:		MAINTENANCE MR-3054 (New Maint. Policy 2018)	
Package No.: 8		Road Id No.: 317851032014	
Status of the Project:		Ongoing/Completed/Under Maintenance	
Work is a case of:		New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	N.A. S/U
b)	Condition of Surfacing	N.A. S/U
c)	Riding Quality	N.A. S/U
d)	Road Camber	N.A. S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No N.A.
f)	Contraction Joints provided or not (CC Pavement)	Yes/No N.A.
g)	Compaction of flank/slope & raincuts if any	Yes/No N.A.
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U N.A.
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U N.A.
c)	Condition of railings/slab/approach for Bridges	S/SRI/U N.A.
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No N.A.
4.	Compliance History	
a)	Status of ATR's & any others	N.A.

Overall Rating :

Satisfactory (S)	'S'
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Note :- Agreement done on 8/12/20
Work has not been started yet.


 05/12/20
 (Signature)

NAME: Shyam Sanjay

DESIGNATION: A.E.
Chh.

A. G.