FIELD INSPECTION REPORT

Date of Inspection: 05.12'20			District: East Champarran		
Division recommended to the second se			Length (km): 2'46		
Name o	f the Road: Pw	Droad at Matte	rchowk to Exdori		
Scheme	Programme:	MAINTENANCE	WK-3024 (HEM HOW! YOU		
Package No.:		5	Road Id No.: 317851032016		
and the second of the second o	of the Project:		ed/Under Maintenance	اسد الاستندا	
Work is	a case of:	the second secon	/Up gradation/ Maintenance		
Sl. No.	Parameters to be checked			Remarks	
1.	Pavement				
a)	Road Junction condition			N. A.	
b)	Condition of Surfacing			N.A.S/U N.A.S/U N.A.S/U	
c)	Riding Quality			N.AS/U	
d)	Road Camber			N. 8/!!	
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.				
f)	Contraction Joints provided or not (CC Pavement)			N. A.No	
g)	Compaction of flank/slope & raincuts if any			Yes No	
2.	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its painting S/SR			S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U	
c)	Condition of railings/slab/approach for Bridges			S/SBIZU	
3.	Road Furniture				
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained				
4.	Compliance History			/	
a)	Status of ATR's	s & any others		N·A	

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	S'
Unsatisfactory (U)	

Note: Agreement done on 13/8/20 Work has not been startedos yet.

NAME:

Shyam Suder Raig A.E.

DESIGNATION: