## FIELD INSPECTION REPORT

Date of Inspection: 05, 12, 20 District: East cham para  Length (km): 3.56 x 4				
Date of				
Division	·			
Name o	fthe Road: Sripur to Kudarket  Programme: MAINTENANCE MR-3054 (Nea Hairt Polis  Programme: MAINTENANCE MR-3054 (Nea Hairt Polis  Programme: MAINTENANCE MR-3054 (Nea Hairt Polis  Programme: New 11 No.: 2178512 3	cy 2018)		
Koad to 1100 31 10 3 10				
Package No.: 6 Opposite/Completed/Under Maintenance				
New Connectivity/Up gradation/ Maintenance				
Sl. No.	Parameters to be checked	Remarks		
1.	Pavement	and the second s		
a)	Road Junction condition	M.AU.		
b)	Condition of Surfacing	N.S.U		
	Riding Quality	N.A.		
	Road Camber	N.A.		
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No		
f)	Contraction Joints provided or not (CC Pavement)	XS:ANO		
g)	Compaction of flank/slope & raincuts if any	N/es/No		
2.	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting	S/SBI/U		
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	Ns/sri/u		
c)	Condition of railings/slab/approach for Bridges	SISBUU		
3.	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No N.A.		
4.	Compliance History			
a)	Status of ATR's & any others	N.A.		

Overall Rating

Satisfactory (S)	151	
	<b>A</b>	
Satisfactory but requires Improvement (SRI)		
Unsatisfactory (U)		

Note: - Agreement done as 13/8/20 Work has not been Harded

OS 12120 (Signature)

NAME:

Shyam Suh Roy'

A-E

DESIGNATION:

11<u>E1</u>