

FIELD INSPECTION REPORT


Date of Inspection : 05.12.20		District: East Champaran
Division : Paxam		Length (km): 3.25 KM
Name of the Road: Bahadurpur to Baishakhwa		
Scheme/Programme: MAINTENANCE	Road Id No.: 317851032020	
Package No.: 3054-MR-06	New Maintenance Policy 2018	
Status of the Project: <input checked="" type="checkbox"/> Ongoing/Completed/Under Maintenance		
Work is a case of: <input checked="" type="checkbox"/> New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	N.A. S/U
b)	Condition of Surfacing	N.A. S/U
c)	Riding Quality	N.A. S/U
d)	Road Camber	N.A. S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No N.A.
f)	Contraction Joints provided or not (CC Pavement)	Yes/No N.A.
g)	Compaction of flank/slope & raincuts if any	Yes/No N.A.
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	N.A. S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	N.A. S/SRI/U
c)	Condition of railings/slab/approach for Bridges	N.A. S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No N.A.
4.	Compliance History	
a)	Status of ATR's & any others	N.A.

Overall Rating :

Satisfactory (S)	'S'
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Note:- Agreement done on 13/8/20
work has not been started
as yet.


05/12/20
(Signature)

NAME: Shyam Sunder Puri

DESIGNATION: A.E. / Ch.