

FIELD INSPECTION REPORT

Date of Inspection : 6/12/2020	District: Yamou
Division : W Division Yamou	Length (km): 1.650 Km.
Name of the Road: Yamou districtal path to Bakro (Yamou road)	
Scheme/Programme:	MAINTENANCE
Package No.: MR-N/19-20/Yamou/M	Road Id No.: 28411032536
Status of the Project:	Ongoing/Completed/Under Maintenance
Work is a case of:	New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U N/A
b)	Condition of Surfacing	S/U N/A
c)	Riding Quality	S/U N/A
d)	Road Camber	S/U N/A
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
	Compliance History	
a)	Status of ATR's & any others	N/A

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME:

DESIGNATION:

Prasad
6/12/2020

Ag. Km
6/12/20
(Signature) A2