

FIELD INSPECTION REPORT

Date of Inspection : 6/12/2020	District: Yamou
Division : (W) Division Yamou	Length (km): 3.248 km
Name of the Road: Yamou Sikandara Dam to Padanuat	
Scheme/Programme: MAINTENANCE	
Package No.: M.R.-N/19-2/Yamou	Road Id No.: 28411032559
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Remarks	
Preventive	
a) Road Junction condition	✓S/U
b) Condition of Surfacing	✓S/U
c) Riding Quality	✓S/U
d) Road Camber	✓S/U
e) Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f) Contraction Joints provided or not (CC Pavement)	Yes/No
g) Compaction of flank/slope & raincuts if any	Yes/No
Structural	
a) Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b) Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c) Condition of railings/slab/approach for Bridges	S/SRI/U
Road Furniture	
a) Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓Yes/No
Compliance History	
a) Status of ATR's & any others	N/A

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME:

DESIGNATION:

Prodel
6/12/2020

(Signature) *Ask*
6/12/2020