FIELD INSPECTION REPORT

Date of Ins	pection: 0	6/12/2020	District: Jamue	
Division :	Jamm'	T V	Length (km): 2.00 14 H	
vame of th	e Road: kha	regard Manikway	Road to Gurhaya Mushard, Mi	
cheme/Pr	ogramme:	MAINTENANCE	via Nichali kharsani &	Gurlia Mu
Package No.: MR-N 19-2 / Januar 13 Status of the Project: Ongoing Completed			d/Under Maintenance	
lkNo.	在2000年的		be elle Ukro	Remarks
1 1	avement			
a) F	Road Junction condition			SAU N
b) (Condition of Surfacing			SAU AN
	Riding Quality			S/U N
	Road Camber			SAU NI
	to the state or the state of th			Yes/No
	Contraction Joints provided or not (CC Pavement)			Yes/No
	Compaction of flank/slope & raincuts if any			Yes/No
SAL-TINGUESIDE INC	Cross Drainage			
a) (Condition of head walls in Hume pipe culverts including its painting			S/SRI/U
				S/SRI/U
1	Condition of railings/slab/approach for Bridges			S/SRI/U
N.C.	Road Curniture			
	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained Yes/No			Yes/No
	Compilance History			
a) S	Status of ATR's & any others			MIA
				On-going!
Overall Rating :		Satisfactory (S)		
			requires Improvement (SRI)	
		Unsatisfactory (U))	V 1

Supta 06/12/2020 5-E (Jay prakash Gripts) (Signature)

NAME:

DESIGNATION: