## FIELD INSPECTION REPORT

Date of I	nspection:	112 2020	District: James	
Division: Janui			Length (km): 12.000	
Name of		rdimore to B	abudih via chaunkitamr,	Tundo Asaboros
Scheme/	Programme:	MAINTENANCE		
		4-20 Janui /15	Road Id No.: 284110325	591
			ed/Under Maintenance	
DEPOSITO	a case of:		Up gradation/ Maintenance	HS COMMENT DATES
SINO		Varametersu	o be checked	Remarks
1	Pavement	<b>Positiva</b>		
a)	Road Junction condition			S/U N/A
b)	Condition of Surfacing			S/U H/A
c)	Riding Quality			S/U W/A
d)	Road Camber			S/U W/A
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
f)	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any			Yes/No
	Cross Drain a	ge (The second		
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U 14/
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
c)	Condition of railings/slab/approach for Bridges			S/SRI/U
	Road Familiare			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			Yes/No
湖州海	genomini e	niday = 33 g		
a)	Status of ATR's & any others			MIA
Overall Rating : Satisfactory (S)		iong	oly ·	
				0
Satisfactory but			t requires Improvement (SRI)	

Unsatisfactory (U)

NAME:

**DESIGNATION:** 

(Signature)