		FIELD INSPECTION	REPORT		
Pate Of Inspection 03/12/2026 District 13			ofper		
ivision	PIR	0	District 24	1.240	
Name of the Road:		REO Road Ja	REO Road Joifpura to That		
Scheme/Programme		MAINTENANCE			
ackage	No.: MR-M	1-20110/14	oad Id No.:		
Status of the Project :		i .	Ongoing/Completeted/Under Maintenance		
Vork is	a case of :	New, Connectivity/Up	gradation/Maintenance		
I No.	,	Parameters to be checked	d	Remarks	
	Payment /	goeconcut orag	+ done		
)	Road Junction condition			S/U	
)	Condition of Surfacing			S/U	
c)	Riding Quality			S/U	
d)	Road Camber			S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement			Yes/No	
f)	Contraction Joints provided or not (CC Pavement)			Yes/No	
g)	Compaction of flank/slope & raincuts if any			Yes/No	
2	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U	
b)	Condition of Abutment & Wing walls, Slab in RCC oulverts			S/SRI/U	
0)	Condition of railings/slab/approach for Bridges			S/SRI/U	
3	Road Furniture				
a)	Whether sign boards/informatory/cautionary Board/km & 200m Yes/ stones/Pavement road markings are provided and maintained			Yes/No	
4	Compliance History				
a)	Status of ATR's & any others				

_	2		-
Overs	1	12.42	4

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Namo: Timesh chandhoroy

Freeligination J.E.