

FIELD INSPECTION REPORT

Date of Inspection : 04/12/20	District: Nawada
Division : Nawada	Length (km): 2.00 km
Name of the Road: main road Nawada, Civil court to NH 31 Baidhaur	
Scheme/Programme: MAINTENANCE	
Package No.: MR-N/19-20/NWD/11	Road Id No.:
Status of the Project: ☒ Ongoing/ ☐ Completed/ ☐ Under Maintenance	
Work is a case of: ☒ New Connectivity/ ☐ Up gradation/ ☐ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U N.A.
b)	Condition of Surfacing	S/U N.A.
c)	Riding Quality	S/U N.A.
d)	Road Camber	S/U N.A.
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No N.A.
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of A/R's & any others	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Remarks :- work in progress

(Signature)

J.E. Nawada

NAME: SUSIT KUMAR