		FIELD INSPECTION RE	PORT	
Date of Inspection:		05/12/2020	District : BHALHALPUR	
Division:		NAVWACHHEA	Length (km): 3.350 km	
Name of the Road:		NH-31 TO Askai Tola.		
Scheme/Programme:		Maintenance de la saintenance policy 2019		
		Maintenance New maintenance policy 2018 MR-M/2019-20 HAVUIA CHMIA/11 Road Id No.:		
Package No.:		MR-M 2019-20 NAVUIA CHAIR[1]		
Status of the Project:		Qngoing/Completed/Under Maintenace		
Work is a case of:		New Connectivity/Up gradation/Maintenance		
SI. No.		Parameteres to be cheeked		Remarks
1	Pavement			S/U
a)	Road Junction	tion condition		
b)	Condition of S	of Surfacing		
c)	Raod Quality			S/U
d)	Road Camber			S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Payement.			Yes/No
f)	Contraction Joints provided or not (CC Pavement)		Yes/No	
g)	Conpaction of	Conpaction of flank/slope & raincuts if any		
2	Cross Drainage Condition of head walls in Hume pine culvert including its painting. S/SRI/U			
a)	Condition of	n of head walls in Hume pipe culvert including its painting.		
b)	Condition of	dition of Abutment & Wing walls, Slab in RCC culverts.		
c)		on of railings/slab/approach for Bridges		
3	Cross Drainag	s Drainage		
a)	Whether sign boards/infomatory/caultionaty Boards/km & 200m stones/Pavements roads marking are provided and maintained. informatory board has been lived and wife			
4	Compliance History			
a)	Status of ATR's & any others			

Overall Rating:

Satisfactory (S)	NA
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Remarks - House work not started.

NAME: Marondra Kumo

DESIGNATION: ASSISTANL E Tylan

(Signature) (Signature) प्रिटियंक अभियंता
ग्रामीण कार्व विभाग
कार्य अवर प्रनंडल नारायणपुर