

(Block - Shahmud)

FIELD INSPECTION REPORT

Date of Inspection:	03/12/2020	District:	Bhagalpur
Division:	Bhagalpur	Length (Km):	2.50 km
Name of the Road:	Maho Ashay to Sarha.		
Scheme/Programme:	MAINTENANCE		
Package No. / Group No. - 11	Road Id No.: 27321032926		
Status of the Project:	Ongoing / completed / Under Maintenance		
Work is a case of :	New Connectivity / Up gradation / Maintenance		
SL. No.	Parameters to be checked	Remarks	
1	Pavement		
a)	Road Junction condition	S/U	NA
b)	Condition of Surfacing	S/U	NA
c)	Riding Quality	S/U	NA
d)	Road Camber	S/U	NA
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	NA
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	NA
g)	Compaction of flank/slope & raincuts if any	Yes/No	NA
2	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	NA
b)	Condition of Abutment & Wing Walls, Slab in RCC culverts	S/SRI/U	NA
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	NA
3	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No	NO
4	Compliance History		
a)	Status of ATR's & any others		NO

Overall Rating :

Satisfactory(S)	—
Satisfactory but requires Improvement (SRI)	SR2
Unsatisfactory(U)	—

NAME: Neera Kumar

03/12/2020
(Signature)

DESIGNATION: J-E