

FIELD INSPECTION REPORT

Date of Inspection :	05/12/2018	District :	East Champaran
Division :	Chakia	Length (Km):	2.00 km
Name of the Road :	Bahadurpur to Kataria		
Scheme/Programme :	MAINTENANCE (New Maintenance policy 2018)		
Package No.:		Road ID No.:	
Status of the Project :	Ongoing/Completed/Under Maintenance		
Work is a case of :	New Connectivity/Up Gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	—
b)	Condition of surfacing	—
c)	Riding Quality	—
d)	Road Camber	—
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	—
f)	Contraction Joints provided or not (CC Pavement)	—
g)	Compaction of flank/slope & raincuts if any	—
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	—
b)	Condition of Abutment & Wing walls, Slab in RCC Culverts	—
c)	Condition of railings/slab/approach for Bridges	—
3.	Road Furniture	
a)	Whether sign board/informatory/cautionary Board/Km & 200m Stones/Pavement road markings are provided and maintained	—
4.	Compliance History	—
a)	Status of ATR's & any others	—

Overall Rating :	Satisfactory (S)	—
	Satisfactory but requires improvement (SRI)	—
	Unsatisfactory (U)	—

Not - work has been not started yet.

Zaki
05/12/2020
JE

05/12/2020
A.E

(Signature)

NAME :

DESIGNATION :

Zaki
05/12/2020
JE

05/12/2020
A.E