

FIELD INSPECTION REPORT

Date of Inspection :	4.12.2020	District:	Garh
Division :	Sompur	Length (km):	1.70 K.M.
Name of the Road:	Harinath path, G29 path, Nohath Mandir se Parvati Badi Bardura hi village Tak.		
Scheme/Programme:	MAINTENANCE — M.R		
Package No.:	M.R-N/9-20 Sompur-18	Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance M.R New pol. of 2018		
Work is a case of:	New Connectivity/Up gradation/ Maintenance M.R		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	Work just started do to flood and rain.
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI ✓
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI U H A r
c)	Condition of railings/slab/approach for Bridges	S/SRI U H A r
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	N

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

(Signature)
J-C

NAME: Kari Ram

DESIGNATION: J.C. Sompur