	Aspection 12/20 District : Bhagalpur		
-	Length (Km): 0.6		1 1 4 4 42
-	: Bhagalpur me Akceble	nagar	rood.
100	TANCE O	San San Carlo	
Scheme /	Programme: MAINTENANCE	2368	5
ackage l	No.: 920cep - 1 9 Road Id No.: 27 32 c	c love	cess.
tatus of	the Project: Ongoing / Completed / Under Maintenance	3 . 10	
	case of: New Connectivity / Up gradation / Maintenance		
SL. No. Parameters to be checked		Remarks	
1.	Pavement	T 0/11	^
a)	Road Junction condition	S/U	
b)	Condition of Surfacing	S/U	
c)	Riding Quality	S/U	_
d)	Road Camber	S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavernent.	Yes / No	11/.
ŋ	Contraction Joints provided or not (CC Pavement)	Yes / No	17/4
g)	Cpmpaction of flank/slope & raincuts if any	Yes / No	
2.	Cross Drainage	T	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	
b)	Condition of Abutment & Wing Walls, Slab in RCC culverts	S/SRI/U	
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	
3.	Road Furniture		
a)	Whether sign boards / informatory / cautionary Board / Km & 200m stones Pavement road markings are provided and maintained.	Yes / No	<u>'/</u>
4.	Compliance History		
a)	Status of ATR's & any others		
erall Ra	uing: A. A given & This Boad is in	Markes	tonder pour
te _g .	Satisfactory (S)		
	Satisfactory but requires Improvement (SRI)	NA	
	Unsatisfactory (U)		

NAME: Radka Raman Singh DESIGNATION: