## FIELD INSPECTION REPORT

1

si	ion: Bhagalpur   Length (Km): D. 8 & D			
1	of the Road: Prathmik Swantay Ke	adra T	o kawasiya	
Schem	ne / Programme :   MAINTENANCE			
Packag	ge No.: group -19   Road Id No.: 97321	03368	8	
Status (	ge No.: 9   Road Id No.: 2732    of the Project:   Ongoing / Completed / Under Maintenance (.	5. bre	cess	
11, 10, 1	s a case of:   New Connectivity / Up gradation / Maintenance	5 6		
SL. No			Remarks	
1.	Pavement		<b>,</b>	
a)	Road Junction condition	S/U		
b)	Condition of Surfacing	S/U		
c)	Riding Quality	S/U		
d)	Road Camber	S/U		
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes / No		
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	1 1/4	
g)	Cpmpaction of flank/slope & raincuts if any	Yes / No	,	
2.	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U		
b)	Condition of Abutment & Wing Walls, Slab in RCC culverts	S/SRI/U		
c)	Condition of railings/slab/approach for Bridges	S/SRI/U		
3.	Road Furniture	,		
a)	Whether sign boards / informatory / cautionary Board / Km & 200m stones Pavement road markings are provided and maintained.	Yes / No		
	Compliance History			
1)	Status of ATR's & any others			
all Rat	ing: A-A Jueny Tuis soul is	in unde	s tealer p	
	Satisfactory (S)			
	Satisfactory but requires Improvement (SRI)		7/1	
$\neg$	Unsatisfactory (U)	1/		

NAME:

Rudha Raman Singh

(Signature)

KR