


FIELD INSPECTION REPORT

Date of Inspection: 05/12/20		District: Bhagalpur	
Division: Bhagalpur		Length (Km): 2.050	
Name of the Road: DMHSY Shatapur Tumauri road to Telidih			
Scheme / Programme: MAINTENANCE			
Package No.: group -20		Road Id No.: 27321033852	
Status of the Project: Ongoing / Completed / Under Maintenance C.S. process.			
Work is a case of: New Connectivity / Up gradation / Maintenance			
SL. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	S / U	N/A
b)	Condition of Surfacing	S / U	
c)	Riding Quality	S / U	
d)	Road Camber	S / U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes / No	
f)	Contraction Joints provided or not (CC Pavement)	Yes / No	
g)	Compaction of flank/slope & raincuts if any	Yes / No	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S / SRI / U	
b)	Condition of Abutment & Wing Walls, Slab in RCC culverts	S / SRI / U	
c)	Condition of railings/slab/approach for Bridges	S / SRI / U	
3.	Road Furniture		
a)	Whether sign boards / informatory / cautionary Board / Km & 200m stones / Pavement road markings are provided and maintained.	Yes / No	
4.	Compliance History		
a)	Status of ATR's & any others		
Overall Rating: A A given & This road is under tender process			
	Satisfactory (S)		
	Satisfactory but requires Improvement (SRI)	N/A	
	Unsatisfactory (U)		

NAME: Radha Raman Singh
DESIGNATION: A.E

(Signature) 
05/12/20
AR