FIELD INSPECTION REPORT

		But the State of Court State of Court State of S	
	spection 0 5 12/20 District : Bhagalpur		
4	a: Bhagalpur Length (Km): 5.650	11 -11 0	and legae
4e	of the Road: Kabai byr kasaili q Pr	1 casy 1	jadav Ke
chem	e / Programme : MAINTENANCE	31 /	
Packag	No.: 920cep -20 Road Id No.: 2732 0	33884	
	e No.: 9 cmp - 20 Road Id No.: 2 7 32 6 f the Project: Ongoing / Completed / Under Maintenance C.	5. bre	ass
	a case of: New Connectivity / Up gradation / Maintenance		
SL. No	Parameters to be checked	Remarks	
1.	Pavement		
a).	Road Junction condition	S/U	
b)	Condition of Surfacing	S/U	
c)	Riding Quality	S/Ü	
d)	Road Camber	S/U	7
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes / No	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	
g)	Cpmpaction of flank/slope & raincuts if any	Yes / No	<u>.</u> .
2.	Cross Drainage		14/4
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	
b)	Condition of Abutment & Wing Walls, Slab in RCC culverts	S/SRI/U	
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	
3.	Road Furniture		
^\	Whether sign boards / informatory / cautionary Board / Km & 200m stones / Pavement road markings are provided and maintained.	Yes / No	
4.	Compliance History		
a) :	Status of ATR's & any others		
all Rat	ing: A. A given & This poud is in wa	noter tea	der proces
	Satisfactory (S)	Y	
	Satisfactory but requires Improvement (SRI)	4/4	
. I	Unsatisfactory (U)		

NAME: Radha Raman Bigge DESIGNATION: A.E (Signature) 04/1420

Scanned with CamScanner

4