FIELD INSPECTION REPORT

	spection 05 12 20 District : Bhagalpur		
-	on: Bhagalpur Length (Km): 0. 400		
1000	the Road: Klandyahiya banchayat sask	ain R	awan (shi
cheme /	Programme: MAINTENANCE	10 11 -	
ackage l	No.: 9200 - 19 Road Id No.: 2732 05 the Project: Ongoing / Completed / Under Maintenance C - 5	13 900	
atus of	the Project: Ongoing / Completed / Under Maintenance	- pro	cess.
ork is a	case of: New Connectivity / Up gradation / Maintenance		
L. No.	Parameters to be checked		Remarks
1.	Pavement		
a)	Road Junction condition	S/U	
b)	Condition of Surfacing	s/U	
c)	Riding Quality	S/U	
d)	Road Camber	S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes / No	N/A
Ŋ	Contraction Joints provided or not (CC Pavement)	Yes/No	
g)	Cpmpaction of flank/slope & raincuts if any	Yes / No	
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	
b)	Condition of Abutment & Wing Walls, Slab in RCC culverts	S/SRI/U	
c)	Condition of railings/slab/approach for Bridges	S/SRI/U	
3.	Road Furniture		
a)	Whether sign boards / informatory / cautionary Board / Km & 200m stones / Pavement road markings are provided and maintained.	Yes / No	
4.	Compliance History		
a)	Status of ATR's & any others		
erall Ra	ating: A. A given & This soul is in	Under	tenler ps
	Satisfactory (S)		
9.5	Satisfactory but requires Improvement (SRI)	1	/A
	Unsatisfactory (U)		+

NAME: Radka Raman Singh DESIGNATION: A.E

(Signature) NR

Scanned with CamScanner