

FIELD INSPECTION REPORT

Date of Inspection :	4.12.2020	District:	Saron
Division :	Sonpur	Length (km):	0.700 K.M.
Name of the Road:	House of RAJU Kumar To House of Dina Rai		
Scheme/Programme:	MAINTENANCE	M.R	
Package No.:	M.R-N/19-20 Sonpur-18	Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance M.R		
Work is a case of:	New Connectivity/Up gradation/ Maintenance M.R. New policy 2018		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	SU
b)	Condition of Surfacing	SU
c)	Riding Quality	SU
d)	Road Camber	SU
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No ✓
f)	Contraction Joints provided or not (CC Pavement)	Yes/No NA
g)	Compaction of flank/slope & raincuts if any	Yes/No NA
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U NA
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U NA
c)	Condition of railings/slab/approach for Bridges	S/SRI/U NA
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No work in progress
4.	Compliance History	
a)	Status of ATR's & any others	N

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

NAME: Kari Ram

DESIGNATION: J.E. Sonpur

(Signature)
T. B.