

FIELD INSPECTION REPORT

Date of Inspection :	06-12-2020	District:	Vai'shali
Division :	Mathur	Length (km):	0.750
Name of the Road:	PMGSY road to Kharikafola near Ramhar Singh		
Scheme/Programme:	MAINTENANCE		
Package No.:	M/R-H/19-20/mathur/-12	Road Id No.:	—
Status of the Project:	Ongoing/Completed/Under Maintenance (Work not Started)		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	N.A S/U
b)	Condition of Surfacing	N.A S/U
c)	Riding Quality	N.A S/U
d)	Road Camber	N.A S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	N.A Yes/No
f)	Contraction Joints provided or not (CC Pavement)	N.A Yes/No
g)	Compaction of flank/slope & raincuts if any	N.A Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	N.A S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	N.A S/SRI/U
c)	Condition of railings/slab/approach for Bridges	N.A S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	N.A Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Work not Started

06.12.2020
(Signature)

NAME: SHRABAN KUMAR PRASAD
DESIGNATION: R.W.D.(A.E.)