## FIELD INSPECTION REPORT

	nspection :		District: av 108 ason	the second secon
Division: Lakticason Length (km): 230 Km			The state of the s	
Name of	the Road:		Bhisha Village Rivib	and the state of t
	Programme:	MAINTENANC	The second secon	. 6/1
Package No.: Road Id No.: 284010346  Status of the Project: Ongoing/Completed/Under Maintenance			0-1	
	a case of:		ty/Up gradation/ Maintenance	Remarks
Sl. No.	Parameters to be checked Remark			
1.	Pavement			
a)	Road Junction condition S/U			
b)	Condition of Surfacing S/U			S/U
c)	Riding Quality			S/U
d)	Road Camber			S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			
f)	Contraction Joints provided or not (CC Pavement)  Yes/No			
g)	Compaction of flank/slope & raincuts if any  Yes/No			
2.	Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting S/SRI/U			S/SRI/U
b)				S/SRI/U
c)				S/SRI/U
3.	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			
4.	Compliance History			
a)	Status of ATR's & any others			
Overel	l Rating :			
Overall Rating :		Satisfactory (		
		Satisfactory I	out requires Improvement (SRI)	

This Road is worder Technical Bid.

Unsatisfactory (U)

NAME: Anisur Rochman

DESIGNATION: Executive Engineer

(Signature) (Signature) ग्रामीण कार्य विभाग कार्य प्रमहरू