

FIELD INSPECTION REPORT

Date of Inspection	5/12/20	District	Vishakh
Division	Hydrabad	Length (km)	4.0 Km
Name of the Road	Hurrem sagar ne Pusthal chaur Hat.		
Scheme/Programme	MAINTENANCE	MP	
Package No.		Road Id No.	
Status of the Project	Ongoing ☒ Completed ☐ Under Maintenance ☐		
Work is a case of:	New Connectivity ☐ Up gradation ☐ Maintenance ☒		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	Not fill work in Program

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	-
Unsatisfactory (U)	-


 (Signature)
 BV

NAME:

DESIGNATION: