


FIELD INSPECTION REPORT

Date of Inspection:	06.12.2020	District:	Darbhanga.
Division:	RWD works (DAW) Darbhanga-2	Length(Km):	1.60 K.M.
Name of Road:	L039- Mankauli village to Kathaliya.		
Scheme/Programme:	Maintenance		
Package No.		Road Id No.	
Status of the Project:	Ongoing/Completed/ Under Maintenance		
Work is a case of :	New Connectivity/Up gradation/ Maintenance		
S No.	Parameters to be Checked	Remarks	
1	Pavement		
a)	Road Junction condition	S/U NA	
b)	Condition of Surfacing	S/U NA	
c)	Riding Quality	S/U NA	
d)	Road Camber	S/U NA	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	Yes/No NA	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No NA	
g)	Compaction of flank /slope & raincuts if any	Yes/No NA	
2	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U NA	
b)	Condition of Abutment & Wing walls , Slabs in RCC culverts	S/SRI/U NA	
c)	Condition of railing /slabs/ approach for Bridges	S/SRI/U NA	
3	Road Furniture		
a)	Whether sign boards/ informatory/ cautionary Board / Km & 200m stones/ Pavement road markings are provided and maintained	Yes/No	
3	Compliance History		
a)	Status of ATR's & any others	NA	
Overall Rating:			
Satisfactory (S)		a	
Satisfactory but requires Improvement (SRI)		b	
Unsatisfactory (U)		c	

Till now, work is not started.

Name: KUMAR CHANDRAJ .

Designation: ASST. ENGINEER


 (Signature) 6/12/20