FIELD INSPECTION REPORT

	spection: 05-12-2020 District: Par Shange	
Date of Inspection: 65-12-2020 District: parties g Division: Darshauf - 2 Length (km): 2-9		
Division:	paronaud - 2	
	He Road: ALO REST AND Z. FO NM P 20	518
	TO A LA No.	
Package	No.:	
Status of the Project: Ongoing/Completed/Onder Maintenance Work is a case of: New Connectivity/Up gradation/ Maintenance		the state of the s
SI. No.	Parameters to be checked	Remarks
1.	Payement	TO THE LOCAL PROPERTY OF THE PARTY OF THE PA
	Road Junction condition	S/U
a)		S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	5/0
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
r) + 4. -	Compliance History	
a)	Status of ATR's & any others	

Overall Rating

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	
Not applicable	V

whose not started.

NAME: SYED SHAEQUE AHMAD DESIGNATION: ARSt. Engineer.